09 915132



···
1 05
IPE
/ O /4/2
AUG 1 1 2006
AUG I I LOOS W
\
\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
W. ST
Applicant:
Applicant

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

Applicant:	Jeffrey G. Randall)	PATENT Atty. Docket: SEA00820P01120US
Patent No.:	RE 39,187)	(SC-120 Reissue)
Issued:	July 18, 2006))	
	or: SPURT MINIMIZING DISPENSING STRUCTURE		

REQUEST FOR CERTIFICATE OF CORRECTION OF PATENT FOR MISTAKE
OF THE U.S. PATENT AND TRADEMARK OFFICE (37 C.F.R. §1.322(a))

Commissioner For Patents P. O. Box 1450 Alexandria, VA 22313-1450

Certificate

AUG 1 5 2006

Attention:

Certificate of Corrections Branch

of Correction

Sir:

United States Letters Patent No. RE 39,187 was granted to Jeffrey T. Randall on the basis of the U.S. patent application Serial No. 09/915,132 filed July 25, 2001 as an application to reissue U.S. Patent No. 5,938,087. The Reissue patent is currently assigned to Seaquist Closures Foreign, Inc.

A printing error in the patent was made by the Patent Office as identified on the enclosed Form No. PTO/SB/44 which is submitted herewith in duplicate.

CORRELATION BETWEEN PATENT AND APPLICATION

The correlation between the patent printing error and the application file page/line number location of the error is as follows:

Reissue Patent No. RE 39,187 - - - 2

The patent drawing Sheet 2 of 2 contains the error which is the original FIG. 4 (instead of the FIG. 4 as amended and approved by the Examiner), and the correct patent drawing Sheet 2 of 2 was filed July 23, 2002.

HOW THE ERROR AROSE

The error in the specification drawing arose as a result of the failure of the U.S. Patent and Trademark Office to print the Reissue patent with correct drawing Sheet 2 of 2 (filed July 23, 2002) that contained the "AMENDED" FIG. 4 and that had been approved by the Examiner in the Official Action dated September 23, 2002.

HOW THE ERROR IS TO BE CORRECTED

It is requested that the drawing Sheet 2 of 2 of the U.S. Patent No. RE 39,187 be corrected as now shown on the attached U.S. Patent and Trademark Office Form PTO/SB/44. The undersigned attorney submits that the Certificate of Correction requested herein is appropriate.

THE CORRECTION DOES NOT INVOLVE NEW MATTER

The correction presented in the attached U.S. Patent and Trademark Office Form PTO/SB/44 does not involve a change in the patent that would constitute new matter or would require reexamination.

REQUESTED CERTIFICATE OF CORRECTION COPIES ARE ENCLOSED

In compliance with 35 U.S.C. §254 and 37 C.F.R. §1.322, and to expedite issuance of the requested Certificate of Correction, enclosed herewith are two copies of a proposed U.S. Patent

Reissue Patent No. RE 39,187 - - - - 3

and Trademark Office Certificate of Correction Form PTO/SB/44 setting forth the above-discussed correction.

Also enclosed is a self-addressed stamped return post card.

THE ERROR IS NOT A MISTAKE OF APPLICANT, AND NO FEE SHOULD BE REQUIRED FOR CORRECTION

It is believed that the above-identified printing error is not a mistake of the applicant, and that applicant should not have to pay any fee for issuance of the above-requested Certificate of Correction. Thus, it is believed that this request for a Certificate of Correction is properly presented under 37 C.F.R. §1.322.

AUTHORIZATION TO CHARGE FEE TO DEPOSIT ACCOUNT

If any fee is required for the Certificate of Correction requested herein, you are authorized to charge the fee to Deposit Account No. 23-0785.

Respectfully submitted,

Paul M. Odell Reg. No. 283

Wood, Phillips, Katz, Clark & Mortimer Citicorp Center, Suite 3800 500 West Madison Street Chicago, Illinois 60661-2511 (312) 876-1800

CERTIFICATE OF MAILING

I hereby certify that this paper (along with any paper referred to as being attached or enclosed) is being deposited with the United States Postal Service with sufficient postage at First Class Mail in an envelope addressed to: Attention Certificate of Corrections Branch, Commissioner for Patents, P. O. Box 1450, Alexandria, VA 22313-1450 on August 8, 2006.

Paul M. Odell

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.

(Also Form PTO-1050).

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.:

RE 39,187

Page <u>1</u> of <u>1</u>

APPLICATION NO.:

09/915,132

ISSUE DATE:

July 18, 2006

INVENTOR(S)

Jeffrey T. Randall

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:


In the drawings, Sheet 2 of 2 should be replaced with the attached, new Sheet 2 of 2 which contains the "AMENDED" FIG. 4.


MAILING ADDRESS OF SENDER: (Please do not use customer number below):

Wood, Phillips, Katz, Clark & Mortimer Citigroup Center, Suite 3800 500 West Madison Street Chicago, Illinois 60661 (312) 876-1800 (phone)

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Till will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggesitons for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: ATTENTION CERTIFICATE OF CORRECTIONS BRANCH, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

AUG 15 LUUD





Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.

(Also Form PTO-1050).

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.:

RE 39,187

Page <u>1</u> of <u>1</u>

APPLICATION NO.:

09/915,132

ISSUE DATE:

July 18, 2006

INVENTOR(S)

Jeffrey T. Randall

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

	In the drawings, S	heet 2 of 2 should b	e replaced with th	ie attached, new	Sheet 2 of 2 wh	ich contains
the	e "AMENDED" FIG. 4	•				
ł						
Į						

MAILING ADDRESS OF SENDER: (Please do not use customer number below):

Wood, Phillips, Katz, Clark & Mortimer Citigroup Center, Suite 3800 500 West Madison Street Chicago, Illinois 60661 (312) 876-1800 (phone)

This collection of information is required by 37 CFR 1.322, 1.323, and 1.324. The information is required to obtain or retain a benefit by the public which is to file (and by the USPTO to process an application. Confidentiality is governed by 35 U.S.C. 122 and 37 CFR 1.14. This collection is estimated to take 1.0 hour to complete, including gathering, preparing, and submitting the completed application form to the USPTO. Till will vary depending upon the individual case. Any comments on the amount of time you require to complete this form and/or suggesitons for reducing this burden, should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, U.S. Department of Commerce, P.O. Box 1450, Alexandria, VA 22313-1450. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: ATTENTION CERTIFICATE OF CORRECTIONS BRANCH, Commissioner for Patents, P.O. Box 1450, Alexandria, VA 22313-1450.

